

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2 ਲੇ: ਨਿ: ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ।

ਫੋਨ ਨੰਬਰ 01675-253008

ਈਮੇਲ ਆਈ.ਡੀ. xenpwdmalerkotla@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ

ਗੁਰੂ ਤੇਗ ਬਹਾਦਰ ਪਬਲਿਕ ਸਕੂਲ,

ਬਰੜਵਾਲ, ਧੂਰੀ, ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰਬਰ 16

ਮਿਤੀ: 12/4/2021

ਵਿਸ਼ਾ:- ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

(GURU TEG BAHADUR PUBLIC SCHOOL BARDWAL-DHURI,
DISTT. SANGRUR)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ ਨਿਲ ਮਿਤੀ 05/04/2021

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦੇ ਸਹਾਇਕ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2021-22 (31.03.2022) ਤੱਕ ਬਾਹਰੇ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹਾ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਇਸ ਦਫਤਰ ਦੀ ਜੀ.ਆਰ.ਨੰ.153163 ਮਿਤੀ 06-04-2021 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ/ਸੇਫਟੀ ਰਿਪੋਰਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਲੇ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 64 ਮਿਤੀ 06-04-2021 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

Secretary

Guru Teg Bahadur Public School
Bardwal Dhuri

Principal

Guru Teg Bahadur Public School
Bardwal-Dhuri

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ।


Building Safety Report


Name of School:- GURU TEG BAHADUR PUBLIC SCHOOL BARDWAL-DHURI, DISTT. SANGRUR


As per report of Sh. Sudarsh Kumar Assistant Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:

1. The Parameters to check the stability and safety of building such as Structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof
4. The owner of the etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
5. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
6. A separate certificate regarding Electrical works should be obtained from the competent Authority.
7. Building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
8. This report is for the covered area of the school building 43210.00 Sft which is submitted by the owner of the school building as per drawing.
9. The building of the school is constructed as framed structure/brick masonry.
10. This report is not valid for legal purpose.
11. That the fee charges for the year 2021-2022 is 10,000/-

As per visually inspection as reported by the concerned Assistant Engineer the above building may be used for normal use for One year up to 31-3-2022 subject to the above conditions.


Secretary
Guru Teg Bahadur Public School
Bardwal Dhuri


Principal
Guru Teg Bahadur Public School
Bardwal-Dhuri


Sub-Divisional Engineer,
Const. Sub-Division No2,
PWD B&R Malerkotla.